C Series Count Scale			

SPECIFICATION

C Series										
Rated Capacity	9	2,500	3,000	5,000	6,000	12,000	6,000/15,000	25,000	30,000	
	lb	5	6	10	12	25	12/30	50	60	
Resolution(e)	9	0.5	0.5	I	I	2	2/5	5	5	
Resolution(e)	Ib	0.001	0.001	0.002	0.002	0.005	0.005/0.01	0.01	0.01	
Tare Range	g E	Tare range 50% of full scale								
Weight Range	9	10~2,500	10~3,000	20~5,000	20~6,000	40~12,000	40~15,000	100~25,000	100~30,000	
Weight Kange	lb	0.02 ~ 5	0.02~6	0.04~10	0.04~12	0.1~25	0.1~30	0.2~50	0.2 ~ 60	
Operating Temp., Humidity		-10 °C ~ +40 °C, 85 %								
Requirement Voltas	Denvisore et Milano		AC 220~230 V, 50/60 Hz							
Requirement vota;	<u>2</u> e	AC 10 V, 50/60 Hz								
Power Consumptio	п	10 W								
Platform Size (mm	325 (W)×215 (L)									
Product Size (mm)		340 (W)×350 (L)×130 (H)								
Weight	Veight 4.1 Kg									
Display		One side weight: 5 digit, quantity: 5 digit, unit weight: 6 digit								
Preset Key		15 EA								
* Quantity Shortage	g	12.5	15	25	30	60	75	125	150	
Range	16	0.03	0.03	0.06	0.06	0.2	0.2	0.3	0.3	
* Unit Weight	g	0.33	0.33	0.66	0.66	1.33	1.33	3.33	3.33	
Shortage Range	16	0.001	0.001	0.002	0.002	0.003	0.003	0.007	0.007	

- 1. Introduction
- 2, Insitaliation and Details for Cautious Use
- 3. Name of Each Parts -
- 4, Keyboard Functions
- 5, Display Informations -
- 6, Instructions for Scales Operation -- 6~ 9
- Proceduries to Turn on the Instrument
- Procedures to Set to Zero
- Proceduries to Setup and Deliete the Tare
- Procedures to Count by Setting up the Quantity
 Procedures to Count by Setting up the Unit Weight
- Procedures to Add-up Procedures to Input a Preset Key (PLU Key) with a Unit Weight
- Procedures to Call up the Inputted Unit Weight
- Procedures to Change the Weight Unit

7, Error Indication and Its Information 10

1. Introduction

Thank you for purchasing our C (Count) series Counting scale, This electronic scale, during its process from manufacturing to dispatching, goesthrough aprocess of highly advanced quality care system and it is an outstanding machine, which especially has gone through tho rough quality examination procedures, Before use, please read the instructions manual in order to full yutilize the features of this electronic Scale. We will continue to do our best to provide excellence in weighting practices,

- Installation C ategory II: This instrument is supplied from fixed installation,
 Pollution de gree II: General en vironment without re striction for dust and moisture
- * The protection provided by this scale may be impaired if it is used in am anner not specified by this manual,
- * Possible modifications can be made to this product in the future for quality and feature upgrading purposes.

2

2. Installation and Details for Cautious Use


- Correct Installation Procedures
- This instrument is intended for indoor use only.
- Install in areas with no influence of heat, such as direct ray of light and heater,
- Install away from areas with either strong magnetic force or electrical noise,
- Install on a flat and vibration free platform,
- Install in areas with no dusts and moistures
- Install in areas with no wind currents and radical thermal alterations,
- This instrument is not suitable for use at altitude above 2000m,
- Details for Cautious Use
- Use a soft doth with appliance of alcohol when polishing the scale,
- Keep out water or any liquid type substance from the scale.
- Check to see if the scale is placed horizontally before use, If the scale is not in a horizontal position, use the horizontal positioning adjustment screw in order to adjust its position.
 (The scale is in a horizontal position if a vesicle, inside a leveling indicator located bottom left of the scale, is in the center.)

- When the scale is turned on, the display will be set to initial scaling condition after displaying the word "SCALE". In order to maintain its electrical safeties, warm up the machine for approximately 10 minutes before use. Make sure the weight display is set to "0 g" be fore use. If the display is not set to "0 g", use after setting the display to "0 g" by pushing the "Zero" Key.


- Make sure to turn the power "off" before changing the fuse,
 Make sure to use the key when turning off the scale,
 A safely grounded outlet is strongly recommended for this instrument.

3. Name of Each part





4. Keyboard Functions




Keyboard Functions

Key	Key name	Function	Key	Key name	Function
	Presetkey	Stores the unit price or calls up the unit price.	Q'ty	Quantity Key	Sets up the quantity of the soaled product.
• ~ 9	Number Key	Inputs data.	U nit Wt.	Unit weight Key	8ets up the unit weight of the scaled product.
•	Decima I Point Key	Inputs decimal point.	М	Save Key	8 ave s the unit weight into a preset key.
O	Delete Key	Deletes the imputted data.	Таге	Tare Key	8ets up taue or deletes the tare.
	Total Key	Shows the total add-up quantity.	Zero	Zero Key	8e ts the weight display to "0".
+	Add-up Key	Adds-up the quantities.	0 N / 0 FF	Power Key	Turns the soale on off.
*	Option Key	Rios Q D	•		

4





Disp lay Information

- WEIGHT : Indicates the weight of the scaled product,
- QUANTITY: Indicates the quantity of the scaled product,
- UNIT WEIGHT: Indicates the unit weight of the scale diproduction key inputted data,

RED LED Information


- Zero: Indicated when the weight display is set to "0",
 Tare: Indicated when tare is under setup,
 Short O'ty: Indicated when the quantity of the scaled product is within the "Quantity Shortage Range",
 Short Unit Wt,: Indicated when the quantity of the scaled product is within the "Unit Weight Shortage Range",
 Add: Indicated when the quantites are being added up,
 Ib: Indicated when weight unit is set to "lb",


Protection Earth, Caution and I/O information







I/O : ON/OFF







ε



Warranty Regulations

1.Warranty Information and Term of its Validity.

The scale's breakdown under normal operating condition is guaranteed for a repair with no charge for 1 year from the date of its purchase,

2.Exceptionsfor Guaranteed Service

- Breakdown caused by following reasons are exceptions for guaranteed repair.

 When breakdown cours by repairing or disassembling the scale with one's decision, without any approval from this company or this company's a
- Breakdown caused by lack of user's care.
- Interior remodeling; when damage is made by a person, not affiliated with this company trying to repair of to remodel the inner structure of the scale
- Breakdown and damage caused by not abiding to the cautions during use.
- Breakdown or damage caused by natural disasters such as fire and flood.
- · When the warranty verification is not presented.

3.0 ther.

A warranty Verification without official seal of approval is not valid,

Warranty Verification Seri no If a major company A ddmas Date of dielikely (yg/mo/dy) Balka da pariman i Tel ephone A ddmas Balles accent

Cateo Prinit

Reason for visit In a paction result Inspector